

TABLE OF CONTENTS

1 - FANUC MACROS	1
General Introduction	1
Review of G-codes, M-codes and Subprograms	2
System Parameters	2
Data Setting	2
Custom Macros	3
Probing Applications	3
Overall View	3
Macro Programming	4
Macro Option Check	4
What is a Macro Programming?	4
Typical Features	5
Main Program with Macro Features	5
Using Macros	6
Groups of Similar Parts	7
Offset Control	8
Custom Fixed Cycles	8
Nonstandard Tool Motions	8
Special G-codes and M-codes	8
Alarm and Message Generation	8
Replacing Control Options	9
Hiding and Protecting Macro Programs	9
Probing and Gauging	9
Various Shortcuts and Utilities	9
Skills Requirements	10
2 - BASIC PROGRAM CODES	11
Preparatory Commands	11
Default Settings	11
Modal Values	12
Programming Format	12
Miscellaneous Functions	12
Programming Format	12
M-codes with a Motion	12
Custom M-codes	12
Reference Tables	13
G-codes for Milling	13
Three-Digit G-codes	15
M-codes for Milling	16
G-codes for Turning	16
M-codes for Turning	19
Standard Program Codes	20
Optional Program Codes	20

3 - REVIEW OF SUBPROGRAMS	21
Subprogram Example - Mill	21
Rules of Subprograms	25
Subprogram Repetition	27
Subprogram Nesting	27
Subprogram Documentation	29
Subprograms vs. Macros.	30
Unique Features.	30
CNC Lathe Applications	31
Subprogram Development	32
4 - SYSTEM PARAMETERS	33
What are Parameters ?	33
Saving Parameters	34
Backing Up Parameters	34
Parameter Identification	35
Numbering of Parameters	35
Parameter Classification	35
Parameters Grouping	36
Parameter Display Screen	37
Parameter Data Types.	37
Bit-Type Data Type	37
Relationship of Parameters	40
Byte Data Type	41
Word Data Type.	42
2-Word Data Type	42
Axis Data Type	43
Important Observations.	44
Binary Numbers.	45
Setting and Changing Parameters	46
Protection of Parameters	46
Battery Backup	46
Changing Parameters	47
System Defaults	47
Default Values Settings	48
5 - DATA SETTING	49
Input of Offsets	49
Data Setting Command	50
Coordinate Mode	50
Absolute Mode	50
Incremental Mode	50
Work Offsets.	51
Standard Work Offset Input.	51
Additional Work Offset Input	52
External Work Offset Input	52

Offset Memory Types - Milling	53
Geometry Offset	53
Wear Offset	53
Which Offset to Update?	54
Memory Type A	55
Memory Type B	56
Memory Type C	57
Memory Type and Macros	57
Offset Memory Types - Turning.	58
Adjusting Offset Values	59
Absolute Mode	59
Incremental Mode	59
Tool Offset Program Entry	60
L-Address	60
G10 Offset Data Settings - Milling Examples	61
Valid Input Range	62
Lathe Offsets.	62
P-Offset Number	63
Tip Number Q	63
G10 Offset Data Settings - Turning Examples	64
Data Setting Check in MDI	65
Programmable Parameter Entry	65
Modal G10 Command	66
N-address in G10 L50 Mode	67
P-address in G10 L50 Mode	67
R-address in G10 L50 Mode	67
Program Portability	67
Setting Machine Axes to Zero	70
Bit Type Parameter Example	70
Differences Between Control Models	72
Effect of Block Numbers	72
Block Skip	72

6 - MACRO STRUCTURE

73

Basic Tools	73
Variables.	74
Functions and Constants	74
Logical Functions	74
Defining and Calling Macros.	75
Macro Definition	75
Macro Call	75
Arguments	77
Visual Representation	78
Macro Program Numbers	79
Macro Program Protection	79
Setting Definitions	79
Program Numbers - Range O0001 to O7999	80
Program Numbers - Range O8000 to O8999	80
Program Numbers - Range O9000 to O9999	81
Program Numbers - Range O9000 to O9049	82
Difference Between the O8000 and O9000 Program Numbers	82

7 - CONCEPT OF VARIABLES **83**

Types of Macro Variables	83
Variables in Macros	84
Definition of Variables	84
Calculator Analogy	84
Variable Data	84
Variable Declaration	85
Real Numbers and Integers.	85
Variable as an Expression	86
Usage of Variables	86
Decimal Point Usage	87
Metric and English Units	88
Least Increment	88
Positive and Negative Variables	89
Syntax Errors	90
Restrictions	90
Custom Machine Features	92

8 - ASSIGNING VARIABLES **93**

Local Variables	93
Defining Variables	93
Clearing Local Variables	94
Assigning Local Variables	94
Assignment List 1 - Method 1	94
Assignment List 2 - Method 2	95
Missing Addresses	97
Disallowed Addresses	98
Simple and Modal Macro Calls	98
Selection of Variables	99
Main Program and Local Variables	101
Local Variables and Nesting Levels	105
Common Variables	106
Volatile and Nonvolatile Memory Groups.	106
Input Range of Variables	107
Out-of-Range Values	107
Calculator Analogy.	107
Set Variable Name Function SETVN	108
Protection of Common Variables	108

9 - MACRO FUNCTIONS **109**

Function Groups	109
Definition of Variables Revisited	110
Referencing Variables	110
Vacant or Empty Variables	111
Axis Motion Commands and Null Variables	111
Terminology	112
Arithmetic Functions.	113
Nesting	113
Arithmetic Operations and Vacant Variables	114
Division by Zero	115

Trigonometric Functions	116
Conversion to Decimal Degrees	116
Available Functions	116
Rounding Functions	117
Rounding to a Fixed Number of Decimal Places	119
FUP and FIX Functions	121
Miscellaneous Functions	122
SQRT and ABS Functions	122
LN, EXP and ADP Functions	124
Logical Functions	124
Boolean Functions	124
Binary Numbers Functions	125
Boolean and Binary Examples.	125
Conversion Functions	126
Evaluation of Functions - Special Test	126
Order of Function Evaluation	128
Approach to Practical Applications	129
Using Local Variables	129
Using Common Variables	133
Speeds and Feeds Calculation	134
10 - SYSTEM VARIABLES	137
Identifying System Variables	137
System Variables Groups	138
Read and Write Variables	138
Displaying System Variables	138
System Variables for Fanuc Series 0	139
Fanuc Model 0 Compared to Other Models	140
System Variables for Fanuc Series 10/11/15	140
System Variables for Fanuc Series 16/18/21	141
Organization of System Variables.	144
Resetting Program Zero.	145
11 - TOOL OFFSET VARIABLES	147
System Variables and Tool Offsets	147
Tool Offset Memory Groups	148
Tool Offset Memory - Type A	148
Tool Offset Memory - Type B	149
Tool Offset Memory - Type C	149
Tool Offset Variables - Fanuc 0 Controls	150
Milling Control FS-0M	150
Turning Control - FS-0T	151
Tool Offset Variables - FS 10/11/15/16/18/21 for Milling.	152
Assignments for 200 Offsets or Less - Memory Type A	152
Assignments for 200 Offsets or Less - Memory Type B	153
Assignments for 200 Offsets or Less - Memory Type C	154
Assignments for More than 200 Offsets - Memory Type A	155
Assignments for More than 200 Offsets - Memory Type B	156
Assignments for More than 200 Offsets - Memory Type C	157

Tool Offset Variables - FS 10/11/15/16/18/21 for Turning	158
Tool Setting	158
Assignments for 64 Offsets or Less - Memory Type A	159
Assignments for 64 Offsets or Less - Memory Type B	160
Assignments for More than 64 Offsets - Memory Type A	161
Assignments for More than 64 Offsets - Memory Type B	162
12 - MODAL DATA	163
System Variables for Modal Commands	163
Fanuc 0/16/18/21 Modal Information	163
Fanuc 10/11/15 Modal Information	163
Preceding and Executing Blocks	164
Modal G-codes	164
Fanuc 0/16/18/21	165
Fanuc 10/11/15.	166
Saving and Restoring Data	167
Saving Modal Data.	167
Restoring Modal Data	168
Other Modal Functions.	168
Fanuc 0/16/18/21	169
Fanuc 10/11/15.	170
13 - BRANCHES AND LOOPS	171
Decision Making in Macros.	171
IF Function	172
Conditional Branching	172
Unconditional Branching	173
IF-THEN Option	174
Single Conditional Expressions	175
Combined Conditional Expressions	176
Concept of Loops	177
Single Process	177
Multiple Process	177
WHILE Loop Structure	179
Single Level Nesting Loop.	179
Double Level Loop.	180
Triple Level Loop	180
General Considerations	181
Restrictions of the WHILE Loop	181
Conditional Expressions and Null Variables	182
Formula Based Macro - Sine Curve	184
Clearing Common Variables	186
14 - ALARMS AND TIMERS	187
Alarms in Macros	187
Alarm Number	187
Alarm Message	187
Alarm Format	188
Embedding Alarm in a Macro	188
Resetting an Alarm	190
Message Variable - Warning, Not an Alarm	190

Timers in Macros	191
Time Information	191
Timing an Event	191
Dwell as a Macro	192
15 - AXIS POSITION DATA	193
Axis Position Terms	193
Position Information	194
16 - AUTO MODE OPERATIONS	195
Controlling Automatic Operations	195
Single Block Control	195
M-S-T Functions Control	196
Feedhold, Feedrate, and Exact Check Control	197
Example of Special Tapping Operation	198
Systems Settings	199
Mirror Image Status Check	199
Interpreting System Variable #3007	200
Controlling the Number of Machined Parts.	202
17 - EDITING MACROS	203
Editing Units	203
Program Comments	203
Abbreviations of Macro Functions	204
18 - PARAMETRIC PROGRAMMING	205
What is a Parametric Programming ?	205
Variable Data	205
Benefits of Parametric Programming	206
When to Program Parametrically	206
Planned Approach to Macro Development.	207
19 - FAMILY OF SIMILAR PARTS	209
Macro Development in Depth - Location Pin	209
Drawing Evaluation	210
Objective of the Macro	210
Part Setup, Tooling and Machining Method	210
Drawing Sketch	211
Standard Program	211
Identify Variable Data	212
Creating Arguments	215
Using Variables	216
Writing the Macro	217
Final Version	218
Macro Improvements	220
20 - MACROS FOR MACHINING	221
Angular Hole Pattern - Version 1	221
Variable Data for Angular Hole Pattern	223
Angular Hole Pattern - Version 2	224

Frame Hole Pattern	226
Variable Data for Frame Hole Pattern	227
Bolt Hole Circle Pattern	229
Variable Data for Bolt Hole Circle Pattern	231
Arc Hole Pattern	233
Variable Data for Arc Hole Pattern	234
Circular Pocket Roughing	236
Variable Data for Circular Pocket Roughing	237
Amount of Stock Left	239
Circular Pocket Finishing	240
Variable Data for Circular Pocket Finishing	241
Slot Machining Macro	244
Variable Data for Slot Machining	245
Circular Groove with Multiple Depth	247
From Subprograms to Macros	248
Macro Version Development	249
Rectangular Pocket Finishing	251
21 - CUSTOM CYCLES	255
Special Cycles	255
Options Available	256
G-code Macro Call	256
M-functions Macro Call	258
G13 Circle Cutting Cycle.	260
Macro Call - Normal	262
Macro Call - as a Special Cycle	262
Detailed Evaluation of Offset Value	264
Counterboring Application	266
22 - EXTERNAL OUTPUT	267
Port Open and Port Close Commands	267
Data Output Functions	268
BPRNT Function Description	268
DPRNT Function Description	269
Parameter Settings - Fanuc 10/11/12/15.	269
Metric vs. Inch Format.	270
Parameter Settings - Fanuc 16/18/21.	271
Structure of External Output Functions	272
Output Examples	273
Blank Output Line	274
Columns Formatting	274
DPRNT Practical Examples	274
Date	274
Time	274
Work Offset	274

23 - PROBING WITH MACROS	275
What is Probing ?	275
Touch Probes	276
Probing Technology Today	276
Probe Calibration	277
Feedrate and Probing Accuracy	277
Probing Devices on CNC Machines	278
In-Process Gauging Benefits	278
Types of Probes	278
Probe Size	279
Probe Selection Criteria	279
Machined Part	279
Control System Capabilities	280
Expected Tolerances	280
Additional and Optional Features	280
Associated Costs	280
CNC Machine Probe Technology	280
Optical Signal Transmission	281
Inductive Signal Transmission	282
Radio Signal Transmission	282
In-Process Gauging	282
Features to be Measured	283
Center Location Measurement	284
Measuring External or Internal Width	286
Measuring Depth	287
Measuring External Diameter	287
Measuring Internal Diameter	287
Measuring Angles	288
Changing of Set Values	288
Calibration Devices	288
Calibrating device - Type 1	288
Calibrating device - Type 2	288
Checking the Calibration Device	289
Centering Macro Example	289
Probe Length Calibration	291
Skip Command G31	293
24 - ADDITIONAL RESOURCES	295
Limitations During Macro Execution	295
Single Block Setting	295
Block Number Search	295
Block Skip Function	295
MDI Operation	296
Edit Mode	296
Control Reset	296
Feedhold Switch	296

Knowledge for Macro Programming	297
General Skills	297
Manual Programming Experience.	298
Math Applications	298
Setup Practices	298
Machining Practices	298
Control and Machine Operation	298
Complementary Resources.	299
Industrial Press, Inc.	299
Internet	299
Practical Programming Approach.	299
Macro Programming Tips	300
25 - MACRO COURSE OUTLINE	301

Macro Course Outline	301
Closing Comments	306
 Index	 307
 WHAT'S ON THE CD-ROM ?	 313
